

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Kitchen Pot Filler	SK	5	-	-	None	-	-
Kitchen Prep	SK	<2.5	-	-	None	-	-
Gym	WF	<2.5	-	-	None	-	-
Main Office	WF	<2.5	-	-	None	-	-
Nurses Office	SK	<2.5	-	-	None	-	-
Nurses Office Bathroom	SK	<2.5	-	-	None	-	-
RM 101	WF	<2.5	-	-	None	-	-
RM 102	WF	<2.5	-	-	None	-	-
RM 103	WF	<2.5	-	-	None	-	-
RM 104	WF	<2.5	-	-	None	-	-
RM 105	WF	<2.5	-	-	None	-	-
RM 106	WF	<2.5	-	-	None	-	-
RM 201	SK	<2.5	-	-	None	-	-
RM 202	SK	<2.5	-	-	None	-	-
RM 203	WF	<2.5	-	-	None	-	-
RM 204	WF	<2.5	-	-	None	-	-
RM 205	WF	<2.5	-	-	None	-	-
RM 206	WF	<2.5	-	-	None	-	-
RM 306	WF	<2.5	-	-	None	-	-
RM 305	WF	<2.5	-	-	None	-	-
RM 304	WF	<2.5	-	-	None	-	-
RM 303	WF	<2.5	-	-	None	-	-
RM 302	SK	<2.5	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
RM 301	SK	<2.5	-	-	None	-	-
Ladies Bathroom	SK	<2.5	-	-	None	-	-
Adult Bathroom	SK	<2.5	-	-	None	-	-
Xerox RM	SK	6.9	-	-	None	-	-
Outside Xerox RM	WF	<2.5	-	-	None	-	-
Mens Bathroom	SK	2.6	-	-	None	-	-
Faculty RM	SK	<2.5	-	-	None	-	-
RM 403	WF	2.8	-	-	None	-	-
RM 404	WF	<2.5	-	-	None	-	-
RM 414	WF	<2.5	-	-	None	-	-
RM 415	WF	3.3	-	-	None	-	-
RM 405	WF	<2.5	-	-	None	-	-
RM 406	WF	<2.5	-	-	None	-	-
RM 416	WF	<2.5	-	-	None	-	-
Library Bathroom	SK	<2.5	-	-	None	-	-
Teacher Resource RM	SK	<2.5	-	-	None	-	-
Rm 402	WF	3.5	-	-	None	-	-
RM 401	WF	2.7	-	-	None	-	-
RM 411	WF	<2.5	-	-	None	-	-
RM 410	WF	<2.5	-	-	None	-	-
RM 409	WF	<2.5	-	-	None	-	-
Girls Dressing RM	SK	<2.5	-	-	None	-	-
Pool Office BR	SK	<2.5	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Boys Dressing RM	WF	5.6	-	-	None	-	-
Outside Filter RM	WF	2.7	-	-	None	-	-
RM 502	WF	3.4	-	-	None	-	-
RM 512	WF	3.1	-	-	None	-	-
RM 503	WF	5.3	-	-	None	-	-
RM 513	WF	<2.5	-	-	None	-	-
RM 504	WF	7.5	-	-	None	-	-
RM 505	WF	3.2	-	-	None	-	-
RM 506 BR	SK	3.2	-	-	None	-	-
BR Outside RM 515	SK	4.7	-	-	None	-	-
All Purpose RM	WF	<2.5	-	-	None	-	-
Science RM	SK	<2.5	-	-	None	-	-
Outside Main Entrance	SP	13	-	-	None	-	-
Kitchen Serving Line Handwash	SK	<2.5	-	-	None	-	-
Kitchen Handwash	SK	<2.5	-	-	None	-	-
Kitchen Sanitizer @ (A)	SK	2.7	-	-	None	-	-
Kitchen Sanitizer @ (B)	SK	<2.5	-	-	None	-	-
Kitchen Sanitizer @ (C)	SK	<2.5	-	-	None	-	-
Kitchen BR	SK	<2.5	-	-	None	-	-
Principal's Office BR	SK	<2.5	-	-	None	-	-
CC By Principal's Office	SS	5.5	-	-	None	-	-
Nurse's Office @ (B)	SK	<2.5	-	-	None	-	-
RM 101 @ (A)	SK	7.6	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
RM 101 @ (B)	SK	6.6	-	-	None	-	-
RM 101 BR	SK	<2.5	-	-	None	-	-
RM 102 @ (A)	SK	<2.5	-	-	None	-	-
RM 102 @ (B)	SK	4.4	-	-	None	-	-
RM 102 BR	SK	<2.5	-	-	None	-	-
RM 103	SK	4.2	-	-	None	-	-
RM 104	SK	4.8	-	-	None	-	-
RM 105	SK	110	<1.0	<1.0	FR	Completed FR	1.6
RM 106	SK	13	-	-	None	-	-
RM 201	WF	12	-	-	None	-	-
RM 201 @ (B)	SK	23	<1.0	<1.0	FR	Completed FR	3.4
RM 202	WF	17	12	2.6	FR	Completed FR	2.5
RM 202 @ (B)	SK	30	<1.0	<1.0	FR	Completed FR	4.8
RM 203 @ (A)	SK	18	<1.0	<1.0	FR	Completed FR	6
RM 203 @ (B)	SK	56	<1.0	<1.0	FR	Completed FR	3.4
RM 204 @ (A)	SK	61	<1.0	<1.0	FR	Completed FR	5.4
RM 204 @ (B)	SK	17	<1.0	<1.0	FR	Completed FR	3.2
RM 205 @ (A)	SK	52	<1.0	<1.0	FR	Completed FR	5.1
RM 205 @ (B)	SK	31	<1.0	<1.0	FR	Completed FR	4.1
RM 206 @ (A)	SK	17	<1.0	<1.0	FR	Completed FR	6.4
RM 206 @ (B)	SK	19	<1.0	<1.0	FR	Completed FR	3.2
RM 306	SK	16	<1.0	<1.0	FR	Completed FR	3.7
RM 305	SK	5.8	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
RM 304	SK	15	-	-	None	-	-
RM 303	SK	9.6	-	-	None	-	-
<b>RM 302 @ (B)</b>	<b>SK</b>	<b>21</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>&lt;1.0</b>
<b>RM 301 @ (B)</b>	<b>SK</b>	<b>22</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>&lt;1.0</b>
CC by Xerox RM	SS	3.8	-	-	None	-	-
Band RM on Stage	SS	<2.5	-	-	None	-	-
Faculty RM	WC	<2.5	-	-	None	-	-
RM 406	SK	3.2	-	-	None	-	-
RM 416	SK	4.8	-	-	None	-	-
<b>RM 405</b>	<b>SK</b>	<b>43</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>&lt;1.0</b>
RM 415	SK	6.2	-	-	None	-	-
RM 404	SK	3.7	-	-	None	-	-
RM 414	SK	7.1	-	-	None	-	-
RM 403	SK	7	-	-	None	-	-
RM 402	SK	<2.5	-	-	None	-	-
RM 411	SK	2.9	-	-	None	-	-
RM 401	SK	<2.5	-	-	None	-	-
RM 410	SK	3.6	-	-	None	-	-
RM 409	SK	<2.5	-	-	None	-	-
CC by RM 409	SS	4.9	-	-	None	-	-
Boiler RM BR	SK	4.7	-	-	None	-	-
Laundry RM	SS	6.3	-	-	None	-	-
Girls Dressing RM	WF	210	<1.0	<1.0	FR	CAP	

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
<b>Girls Dressing RM @ (B)</b>	SK	47	3.3	2.3	FR	Completed FR	28 (2/22/2018) 5.93 (4/20/2018)
Boy's Dressing RM	SK	4.8	-	-	None	-	-
Filter RM	SS	4.2	-	-	None	-	-
RM 502	SK	<2.5	-	-	None	-	-
RM 512	SK	5.7	-	-	None	-	-
RM 503	SK	3.6	-	-	None	-	-
RM 513	SK	<2.5	-	-	None	-	-
RM 504	SK	5.3	-	-	None	-	-
RM 505	SK	5.9	-	-	None	-	-
Science Lab @ (B)	SK	7.3	-	-	None	-	-
Science Lab @ (C)	SK	2.7	-	-	None	-	-
Inside Boiler RM	SP	2.8	-	-	None	-	-
Outside Boiler RM	SP	4.6	-	-	None	-	-
<b>Outside 502</b>	<b>SP</b>	<b>83</b>	<b>1.6</b>	<b>2.6</b>	<b>FR</b>	<b>SIGN</b>	
Outside 500 Wing	SP	11	-	-	None	-	-
Outside RM 513	SP	7.6	-	-	None	-	-
<b>End of 300 Wing</b>	<b>SP</b>	<b>180</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>SIGN</b>	
End of 200 Wing	SP	12	-	-	None	-	-
Kindergarten Wing Outside RM 105	SP	8.6	-	-	None	-	-
Kindergarten Wing Outside Boiler RM	SP	8.9	-	-	None	-	-
<b>Kindergarten Wing Outside by RM 106</b>	<b>SP</b>	<b>61</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>SIGN</b>	
Green House	SS	3.4	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Greenhouse Courtyard South	SP	24	<1.0	<1.0	FR	SIGN	-
Greenhouse Courtyard North	SP	13	-	-	None	-	-
Custodial Area	SS	<2.5	-	-	None	-	-
Custodial Area	WC	<2.5	-	-	None	-	-
Pool Office BR Left	SK	<2.5	-	-	None	-	-

## Code Key

### Remediation Type Codes

FR	=	Fixture replacement
FRSLV	=	Replacement of fixture, supply lines, and valves
FRSLVPA	=	Replacement of fixture, supply lines, valves and plumbing assessment
SIGN	=	Warning sign posting
CAP	=	Remove fixture or cap line

### Room ID Codes

CC	=	Custodian Closet
MPR	=	Multi Purpose Room
Café	=	Cafeteria
Sci	=	Science Lab
PE	=	Physical Ed
BR	=	Bathroom
LR	=	Locker Room
RM	=	Room

### Fixture Type Codes

WF	=	Water Fountain
SK	=	Sink
SS	=	Slop Sink
SP	=	Spigot
PF	=	Pot Filler
HB	=	Hose Bib
IM	=	Ice Machine
WC	=	Water Cooler
SH	=	Shower

### Result Code

ND	=	Not Detected
<	=	Less Than
-	=	No Testing Required
#	=	When seen in the Post Remediation Test Results: after numerous failing tests, the Hashtag is used to show a passing result





Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
1st Floor Faculty BR	SK	10	-	-	None	-	-
Outside Faculty BR	WF	3.4	-	-	None	-	-
3rd Floor Mens BR Outside Elevator	SK	<2.5	-	-	None	-	-
3rd Floor Faculty RM	SK	<2.5	-	-	None	-	-
3rd Floor Faculty RM BR	SK	<2.5	-	-	None	-	-
Outside RM A210	WF	7.5	-	-	None	-	-
Main Office	SK	<2.5	-	-	None	-	-
RM A207	SK	4.3	-	-	None	-	-
<b>RM A206</b>	<b>SK</b>	<b>20</b>	<b>2.8</b>	<b>2.3</b>	<b>FR</b>	<b>Completed FR</b>	<b>71 (2/22/2018)</b> <b>&lt;1.0 (4/20/2018)</b>
2nd Floor Girls BR	SK	2.6	-	-	None	-	-
<b>RM A102</b>	<b>SK</b>	<b>25</b>	<b>2.4</b>	<b>2.3</b>	<b>FR</b>	<b>Completed FR</b>	<b>120 (2/22/2018)</b> <b>43.2 (4/20/2018)</b>
Outside Cafe	WF	2.7	-	-	None	-	-
Kitchen Handwash	SK	15	<1.0	<1.0	None	-	-
<b>Outside RM A111</b>	<b>WF</b>	<b>24</b>	<b>&lt;1.0</b>	<b>5</b>	<b>FR</b>	<b>Completed FR</b>	<b>&lt;1.0</b>
2nd Floor Boys BR	SK	<2.5	-	-	None	-	-
RM A104	SK	<2.5	-	-	None	-	-
RM A105	SK	11	-	-	None	-	-
3rd Floor Faculty Room	WC	<1.0	-	-	None	-	-
CC By Room Room A102	SS	<1.0	-	-	None	-	-
Room A207 Teachers Station	SK	2	-	-	None	-	-
Room A207 Counter @ (A)	SK	1.6	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Room A207 Counter @ (B)	SK	32	1.4	<1.0	FR	Completed FR	59 (2/22/2018) 5.03 (4/20/2018)
Room A207 Counter @ (C)	SK	24	1.1	<1.0	FR	Completed FR	52 (2/22/2018) 4.64 (4/20/2018)
Room A207 Counter @ (D)	SK	12	-	-	None	-	-
Room A207 Counter @ (E)	SK	18	<1.0	<1.0	FR	Completed FR	27 (2/22/2018) 10.3 (4/20/2018)
Room A206 Counter @ (A)	SK	56	2.8	<1.0	FR	Completed FR	46 (2/22/2018) <1.0 (4/20/2018)
Room A206 Counter @ (B)	SK	27	3.6	<1.0	FR	Completed FR	58 (2/22/2018) <1.0 (4/20/2018)
Room A206 Counter @ (C)	SK	29	<1.0	<1.0	FR	Completed FR	82 (2/22/2018) 2.37 (4/20/2018)
Room A102 Teachers Station @ (B)	SK	58	3.7	42	Review Required	Completed FR	34 (2/22/2018) 34 (4/20/2018)
Room A102 Counter @ (A)	SK	16	<1.0	1.5	FR	Completed FR	48 (2/22/2018) 29.2 (4/20/2018)
Room A102 Counter @ (B)	SK	20	<1.0	<1.0	FR	Completed FR	38 (2/22/2018) 22.6 (4/20/2018)
Room A102 Counter @ (C)	SK	40	3.9	3.3	FR	Completed FR	47 (2/22/2018) 23.7 (4/20/2018)
Room A102 Counter @ (D)	SK	18	2.9	1.6	FR	Completed FR	76 (2/22/2018) 26.9 (4/20/2018)
Room A102 Counter @ (E)	SK	52	20	6.3	FRSLV	Completed FR	310 (2/22/2018) 100 (4/20/2018)
Room A102 Counter @ (F)	SK	46	11	7	FR	Completed FR	98 (2/22/2018) 40.2 (4/20/2018)
Room A102 Counter @ (G)	SK	44	13	2.3	FR	Completed FR	68 (2/22/2018) 17 (4/20/2018)
Room A102 Counter @ (H)	SK	49	8	2.7	FR	Completed FR	68 (2/22/2018) 21.4 (4/20/2018)

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Room A102 Counter @ (I)	SK	63	8	12	FR	Completed FR	89 (2/22/2018) 20.9 (4/20/2018)
Room A102 Counter @ (J)	SK	58	7.7	1.8	FR	Completed FR	80 (2/22/2018) 21.7 (4/20/2018)
Prep Room A102	SK	48	2.5	2.3	FR	Completed FR	296 (2/22/2018) 84.2 (4/20/2018)
2nd Floor Boys BR @ (B)	SK	<1.0	-	-	None	-	-
2nd Floor Boys BR @ (C)	SK	<1.0	-	-	None	-	-
2nd Floor Girls BR @ (B)	SK	3.2	-	-	None	-	-
2nd Floor Girls BR @ (C)	SK	<1.0	-	-	None	-	-
Outside Café @ (B)	WF	<1.0	-	-	None	-	-
Room A105 Counter @ (A)	SK	7.1	-	-	None	-	-
Room A105 Counter @ (B)	SK	1.9	-	-	None	-	-
Room A105 Counter @ (C)	SK	2.9	-	-	None	-	-
Room A105 Counter @ (D)	SK	6.9	-	-	None	-	-
Room A104 Unit @ (A)	SK	25	<1.0	<1.0	FR	Completed FR	40 (2/22/2018) 20.1 (4/20/2018)
Room A104 Unit @ (B)	SK	19	<1.0	<1.0	FR	Completed FR	17 (2/22/2018) 13.3 (4/20/2018)
Room A104 Unit @ (C)	SK	3.6	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

## Code Key

### Remediation Type Codes

FR	=	Fixture replacement
FRSLV	=	Replacement of fixture, supply lines, and valves
FRSLVPA	=	Replacement of fixture, supply lines, valves and plumbing assessment
SIGN	=	Warning sign posting
CAP	=	Remove fixture or cap line

### Room ID Codes

CC	=	Custodian Closet
MPR	=	Multi Purpose Room
Café	=	Cafeteria
Sci	=	Science Lab
PE	=	Physical Ed
BR	=	Bathroom
LR	=	Locker Room
RM	=	Room

### Fixture Type Codes

WF	=	Water Fountain
SK	=	Sink
SS	=	Slop Sink
SP	=	Spigot
PF	=	Pot Filler
HB	=	Hose Bib
IM	=	Ice Machine
WC	=	Water Cooler
SH	=	Shower

### Result Code

ND	=	Not Detected
<	=	Less Than
-	=	No Testing Required
#	=	When seen in the Post Remediation Test Results: after numerous failing tests, the Hashtag is used to show a passing result



Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
RM 405	SK	15	1	<1.0	None		
RM 403	SK	3	-	-	None	-	-
Boys BR by Kitchen	SK	5	-	-	None	-	-
Girls BR by Kitchen	SK	3.9	-	-	None	-	-
RM 404	SK	1.6	-	-	None	-	-
RM 408	SK	<1.0	-	-	None	-	-
RM 407	SK	<1.0	-	-	None	-	-
Kitchen Prep	SK	5.6	-	-	None	-	-
Café	WF	<1.0	-	-	None	-	-
RM 401	SK	6.3	-	-	None	-	-
RM 400 (Faculty BR)	SK	3.1	-	-	None	-	-
Outside Room 218	WF	3.4	-	-	None	-	-
Outside Room 204	WF	1	-	-	None	-	-
Faculty BR on 2nd Floor	SK	9.2	-	-	None	-	-
Girls BR on 2nd Floor	SK	1.5	-	-	None	-	-
Faculty BR on 3rd Floor	SK	15	1.9	<1.0	None	Replaced Fixture	1.4 (10/31/2016)
Outside Main Office	WF	2.3	-	-	None	-	-
Faculty Room 1st Floor	SK	<1.0	-	-	None	-	-
Mens Faculty BR 1st Floor	SK	3.6	-	-	None	-	-
Outside Auditorium	WF	<1.0	-	-	None	-	-
Womens Faculty BR 1st Floor	SK	3.3	-	-	None	-	-
Girls BR 1st Floor	SK	1.2	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Boys BR 3rd Floor	SK	1.8	-	-	None	-	-
Girls BR by Lobby	SK	4.6	-	-	None	-	-
Nurse Office	SK	<10	-	-	None	-	-
Outside Nurse Office	WF	<10	-	-	None	-	-
Nurse Office BR	SK	<10	-	-	None	-	-
Outside Fitness Center	WF	<10	-	-	None	-	-
Fitness Center	WF	<10	-	-	None	-	-
Boys BR by Lobby	SK	7.5	-	-	None	-	-
Girls Locker Room	WF	3.6	-	-	None	-	-
Girls Locker Room BR	SK	<10	-	-	None	-	-
PE Office (South) BR	SK	2.2	-	-	None	-	-
Trainers Office	SK	<10	-	-	None	-	-
Outside Boys Locker Room	WF	<10	-	-	None	-	-
Outside Boys Locker Room	SS	3.9	-	-	None	-	-
PE Office (North) BR	SK	3	-	-	None	-	-
Boys Locker Room BR	SK	2.4	-	-	None	-	-
<b>Boys Team Room Coaches Office BR</b>	<b>SK</b>	<b>89</b>	<b>2.8</b>	<b>1.5</b>	<b>FR</b>	<b>Completed FRSLVPA</b>	<b>&lt;1.0</b>
<b>Boys Team Room Coaches Office</b>	<b>SP</b>	<b>2011</b>	<b>367</b>	<b>88</b>	<b>FRSLVPA</b>	<b>CAP</b>	<b>-</b>
Boys Team Room	WF	9.4	-	-	None	-	-
Boys Team Room BR	SK	<10	-	-	None	-	-
By Football Field	WF	<10	-	-	None	-	-
Principals Office BR	SK	5.1	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Wood Shop WF	WF	17	20	10	FRSLV	Completed FRSLV	<1.0
Wood Shop SK	SK	4.5	-	-	None	-	-
Ceramics RM SK	SK	<1.0	-	-	None	-	-
Ceramics RM WF	WF	1.1	-	-	None	-	-
Art RM BR	SK	1.8	-	-	None	-	-
Art RM	SK	2.4	-	-	None	-	-
Room 405 Table 1 @ (A)	SK	12	-	-	None	-	-
Room 405 Table 1 @ (B)	SK	<1.0	-	-	None	-	-
Room 405 Table 1 @ (C)	SK	6.1	-	-	None	-	-
Room 405 Table 2 @ (A)	SK	1	-	-	None	-	-
Room 405 Table 2 @ (B)	SK	4.1	-	-	None	-	-
Room 405 Table 2 @ (C)	SK	11	-	-	None	-	-
<b>Room 405 Counter</b>	<b>SK</b>	<b>19</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>112 (2/22/2018) 24.9 (4/20/2018)</b>
Prep Room 405	SK	11	-	-	None	-	-
Room 403 Table 1 @ (A)	SK	6.2	-	-	None	-	-
Room 403 Table 1 @ (B)	SK	12	-	-	None	-	-
<b>Room 403 Table 1 @ (C)</b>	<b>SK</b>	<b>24</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>9.2</b>
<b>Room 403 Table 2 @ (A)</b>	<b>SK</b>	<b>25</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>24 (2/22/2018) &lt;1.0 (4/20/2018)</b>
Room 403 Table 2 @ (B)	SK	<1.0	-	-	None	-	-
Room 403 Table 2 @ (C)	SK	3.8	-	-	None	-	-
Room 403 Counter	SK	10	-	-	None	-	-
Prep Room 403	SK	3.9	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Room 404 Table 1 @ (A)	SK	121	<1.0	3.4	FR	Completed FR	129 (2/22/2018) 40.2 (4/20/2018)
Room 404 Table 1 @ (B)	SK	182	1.5	3.8	FR	Completed FR	105 (2/22/2018) 17.5 (4/20/2018)
Room 404 Table 1 @ (C)	SK	95	4.3	<1.0	FR	Completed FR	188 (2/22/2018) 17.5 (4/20/2018)
Room 404 Table 1 @ (D)	SK	34	3.3	<1.0	FR	Completed FR	169 (2/22/2018) 27.1 (4/20/2018)
Room 404 Table 2 @ (A)	SK	174	<1.0	<1.0	FR	Completed FR	71 (2/22/2018) 23.6 (4/20/2018)
Room 404 Table 2 @ (B)	SK	144	7.6	<1.0	FR	Completed FR	114 (2/22/2018) 15.2 (4/20/2018)
Room 404 Table 2 @ (C)	SK	88	3.3	<1.0	FR	Completed FR	49 (2/22/2018) 32.1 (4/20/2018)
Room 404 Table 2 @ (D)	SK	80	<1.0	<1.0	FR	Completed FR	53 (2/22/2018) 33.7 (4/20/2018)
Room 404 Table 3 @ (A)	SK	201	3.2	<1.0	FR	Completed FR	37 (2/22/2018) 40.3 (4/20/2018)
Room 404 Table 3 @ (B)	SK	100	<1.0	<1.0	FR	Completed FR	47 (2/22/2018) 59.7 (4/20/2018)
Room 404 Table 3 @ (C)	SK	150	<1.0	<1.0	FR	Completed FR	52 (2/22/2018) 84.8 (4/20/2018)
Room 404 Table 3 @ (D)	SK	190	<1.0	<1.0	FR	Completed FR	88 (2/22/2018) 45.8 (4/20/2018)
Room 408 Table 1 @ (A)	SK	20	<1.0	<1.0	FR	Completed FR	67 (2/22/2018) 27.7 (4/20/2018)
Room 408 Table 1 @ (B)	SK	26	<1.0	<1.0	FR	Completed FR	69 (2/22/2018) 15.9 (4/20/2018)
Room 408 Table 2 @ (A)	SK	11	-	-	None	-	-
Room 408 Table 2 @ (B)	SK	9.8	-	-	None	-	-
Room 408 Table 3 @ (A)	SK	17	5	<1.0	FR	Completed FR	82 (2/22/2018) 23.8 (4/20/2018)

Action Level = 15.0 parts per billion (ppb) (ug/L)



Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Room 408 Table 3 @ (B)	SK	12	-	-	None	-	-
Room 408 Table 4 @ (A)	SK	7.9	-	-	None	-	-
Room 408 Table 4 @ (B)	SK	8.6	-	-	None	-	-
Room 408 Table 5 @ (A)	SK	7.5	-	-	None	-	-
Room 408 Table 5 @ (B)	SK	8.9	-	-	None	-	-
Room 408 Table 6 @ (A)	SK	10	-	-	None	-	-
Room 408 Table 6 @ (B)	SK	8	-	-	None	-	-
Room 408 Counter 1 @ (A)	SK	2.7	-	-	None	-	-
Room 408 Counter 1 @ (B)	SK	3.3	-	-	None	-	-
Room 408 Counter 2	SK	9.6	-	-	None	-	-
Prep Room 408	SK	157	1	<1.0	FR	Completed FR	122 (2/22/2018) 19.4 (4/20/2018)
Prep RM 408 Fume Hood	SK	732	17	2.6	FRSLV	Completed FR	160 (2/22/2018) 51.5 (4/20/2018)
Room 408 Fume Hood	SK	2231			FR	CAP	
Girls BR By Kitchen	SK	<1.0	-	-	None	-	-
CC By Kitchen	SS	<1.0	-	-	None	-	-
Kitchen Handwash (Island)	SK	15			None		
Kitchen Sanitize @ (A)	SK	3	-	-	None	-	-
Kitchen Sanitize @ (B)	SK	4	-	-	None	-	-
Kitchen Handwash	SK	2	-	-	None	-	-
Kitchen BR	SK	7.8	-	-	None	-	-
Room 401 Table 1 @ (A)	SK	5.3	-	-	None	-	-
Room 401 Table 1 @ (B)	SK	5.5	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Room 401 Table 1 @ (C)	SK	3	-	-	None	-	-
<b>Room 401 Counter 1</b>	<b>SK</b>	<b>19</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>91 (2/22/2018) 3.22 (4/20/2018)</b>
Room 401 Counter 2 @ (A)	SK	6.1	-	-	None	-	-
Room 401 Counter 2 @ (B)	SK	<1.0	-	-	None	-	-
3rd Floor Girls BR @ (B)	SK	<1.0	-	-	None	-	-
Hallway 3rd Floor	WF	1.6	-	-	None	-	-
3rd Floor Boys Room @ (B)	SK	<1.0	-	-	None	-	-
3rd Floor CC By Book Room	SS	3.8	-	-	None	-	-
2nd Floor CC By Elevator	SS	14	-	-	None	-	-
<b>Room 203</b>	<b>SK</b>	<b>94</b>			<b>FR</b>	<b>CAP</b>	
2nd Floor Girls BR @ (B)	SK	<1.0	-	-	None	-	-
<b>Library Back Room</b>	<b>SK</b>	<b>24</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>12</b>
<b>Library Work Room</b>	<b>SK</b>	<b>123</b>	<b>1.5</b>	<b>2.5</b>	<b>FR</b>	<b>Completed FR</b>	<b>7.6</b>
Mens Faculty BR @ (B)	SK	9.2	-	-	None	-	-
Womens Faculty BR @ (B)	SK	1.4	-	-	None	-	-
Faculty Room	WC	<1.0	-	-	None	-	-
<b>1st Floor CC By Elevator</b>	<b>SS</b>	<b>16</b>	<b>&lt;1.0</b>	<b>2.2</b>	<b>FR</b>	<b>Completed FR</b>	<b>5</b>
Girls BR By Lobby @ (B)	SK	3.8	-	-	None	-	-
Boys Br By Lobby @ (B)	SK	5.3	-	-	None	-	-
Rifle Range	SS	9.9	-	-	None	-	-
Boys LR CC	SS	3.2	-	-	None	-	-
<b>Boys LR BR @ (B)</b>	<b>SK</b>	<b>17</b>			<b>FR</b>	<b>Completed FR</b>	<b>2.7</b>

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Boys Team RM CC	SS	6.9	-	-	None	-	-
Boys Team RM BR @ (B)	SK	1.4	-	-	None	-	-
Girls LR BR	SK	6	-	-	None	-	-
Girls LR CC	SS	2.1	-	-	None	-	-
<b>Auditorium</b>	<b>SS</b>	<b>16</b>			<b>FR</b>	<b>Completed FR</b>	<b>39 (2/22/2018) 68.8 (4/20/2018)</b>
Custodial Area	SS	<1.0	-	-	None	-	-
Custodial Area BR	SK	1.1	-	-	None	-	-
Custodial Area	WC	<1.0	-	-	None	-	-
<b>CC By Maintenance Area</b>	<b>SS</b>	<b>126</b>	<b>1.8</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>60 (2/22/2018) 3.64 (4/20/2018)</b>
Portable B2	SK	1.3	-	-	None	-	-
Portable B1	SK	8.5	-	-	None	-	-
Wood Shop	SS	3.2	-	-	None	-	-
Ceramics Room @ (B)	SK	5.8	-	-	None	-	-
Ceramics Room @ (C)	SK	<2.5	-	-	None	-	-
Ceramics Room @ (D)	SK	<2.5	-	-	None	-	-
Art Room @ (B)	SK	11	-	-	None	-	-
<b>Art Room @ (C)</b>	<b>SK</b>	<b>22</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>CAP</b>	
Photo Walkthrough @ (A)	SK	<2.5	-	-	None	-	-
Photo Walkthrough @ (B)	SK	5	-	-	None	-	-
Photo Room	SK	3.9	-	-	None	-	-
<b>Dark Room</b>	<b>SK</b>	<b>19</b>	<b>33</b>	<b>14</b>	<b>FRSLV</b>	<b>Completed FR</b>	<b>45 (2/22/2018) 13.8 (4/20/2018)</b>

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Art Room Unit @ (B)	SK	6.2	-	-	None	-	-
Art Room Unit @ (C)	SK	12	-	-	None	-	-
Art Room Unit @ (D)	SK	13	-	-	None	-	-
Art Room Unit @ (E)	SK	7	-	-	None	-	-
Art Room Unit @ (F)	SK	16	1.3	<1.0	FR	Completed FR	6.5
Rear Of Tech Ed	SP	14	-	-	None	-	-
Wrestling Room	WF	<2.5	-	-	None	-	-
Wrestling Room	SK	<2.5	-	-	None	-	-
Wrestling Room	SS	12	-	-	None	-	-
Hose Bib Outside HS Faculty	SP	16	2.7	16	Review Required	SIGN	
Hose Bib Outside Rear Breezeway	SP	5.2	-	-	None	-	-
Hose Bib Outside Kitchen	SP	50			FR	CAP	
Hose Bib Outside Guidance	SP	14	-	-	None	-	-
Hose Bib Outside Gym Lobby Boys BR	SP	<2.5	-	-	None	-	-
Hose Bib Outside Football Stairs	SP	16	15	1.9	FR	SIGN	
Hose Bib By Football Field	SP	<2.5	-	-	None	-	-
Wood Shop @ (B)	SK	23	4.1	1.9	FR	Completed FR	13
Wood Shop @ (C)	SK	30	<1.0	<1.0	FR	Completed FR	68 (2/22/2018) 3.7 (4/20/2018)
Hose Bib Outside Boy's Team LR	SP	94	8.6	2.6	FR	SIGN	

## Code Key

### Remediation Type Codes

FR	=	Fixture replacement
FRSLV	=	Replacement of fixture, supply lines, and valves
FRSLVPA	=	Replacement of fixture, supply lines, valves and plumbing assessment
SIGN	=	Warning sign posting
CAP	=	Remove fixture or cap line

### Room ID Codes

CC	=	Custodian Closet
MPR	=	Multi Purpose Room
Café	=	Cafeteria
Sci	=	Science Lab
PE	=	Physical Ed
BR	=	Bathroom
LR	=	Locker Room
RM	=	Room

### Fixture Type Codes

WF	=	Water Fountain
SK	=	Sink
SS	=	Slop Sink
SP	=	Spigot
PF	=	Pot Filler
HB	=	Hose Bib
IM	=	Ice Machine
WC	=	Water Cooler
SH	=	Shower

### Result Code

ND	=	Not Detected
<	=	Less Than
-	=	No Testing Required
#	=	When seen in the Post Remediation Test Results: after numerous failing tests, the Hashtag is used to show a passing result



Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Kitchen	SK	8.7	-	-	None	-	-
Instructional Secretary	WC	<1.0	-	-	None	-	-
Executive Director BR	SK	22	2	<1.0	FR	Completed FR	41 (2/22/2018) 26.7 (4/20/2018)
Ladies BR	SK	8.5	-	-	None	-	-
Mens BR	SK	17	<1.0	<1.0	FR	Completed FR	2.5
Superintendent Waiting Room BR	SK	15	-	-	None	-	-
Superintendent BR	SK	18	<1.0	<1.0	FR	Completed FR	32 (2/22/2018) 7.14 (4/20/2018)
Board Room	WC	<1.0	-	-	None	-	-
Business Office Coffee Area	SK	<1.0	-	-	None	-	-

## Code Key

### Remediation Type Codes

FR	=	Fixture replacement
FRSLV	=	Replacement of fixture, supply lines, and valves
FRSLVPA	=	Replacement of fixture, supply lines, valves and plumbing assessment
SIGN	=	Warning sign posting
CAP	=	Remove fixture or cap line

### Room ID Codes

CC	=	Custodian Closet
MPR	=	Multi Purpose Room
Café	=	Cafeteria
Sci	=	Science Lab
PE	=	Physical Ed
BR	=	Bathroom
LR	=	Locker Room
RM	=	Room

### Fixture Type Codes

WF	=	Water Fountain
SK	=	Sink
SS	=	Slop Sink
SP	=	Spigot
PF	=	Pot Filler
HB	=	Hose Bib
IM	=	Ice Machine
WC	=	Water Cooler
SH	=	Shower

### Result Code

ND	=	Not Detected
<	=	Less Than
-	=	No Testing Required
#	=	When seen in the Post Remediation Test Results: after numerous failing tests, the Hashtag is used to show a passing result



Lead in Drinking Water Test Results

As of 4/24/18

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results (ppb)
Kitchen	WC	<2.5	-	-	None	-	-
Boiler Room	SS	<2.5	-	-	None	-	-
Mens BR	SK	8.3	-	-	None	-	-
Ladies BR	SK	3.6	-	-	None	-	-
Boys Locker Room @ A	SK	5.7	-	-	None	-	-
Boys Locker Room @ B	SK	8.6	-	-	None	-	-
Boys Locker Room	WF	<2.5	-	-	None	-	-
Boys Coaches Office	SK	8	-	-	None	-	-
Boys Coaches Office	IM	<2.5	-	-	None	-	-
Boys Locker Room	SP	<2.5	-	-	None	-	-
Outside Boys BR	SK	126	<1.0	<1.0	FR	Completed FR	11
Outside Girls BR	SK	16	<1.0	<1.0	FR	Completed FR	6.2
Girls Locker Room @ A	SK	16	<1.0	<1.0	FR	Completed FR	7.2
Girls Locker Room @ B	SK	13	-	-	None	-	-
Girls Locker Room	WF	3	-	-	None	-	-
Girls Locker Room	SS	19	<1.0	<1.0	FR	Completed FR	17 (2/22/2018) <1.0 (4/20/2018)
Girls Coaches Office	SK	22	<1.0	<1.0	FR	Completed FR	6.1
Hose Bib By Main Entrance	SP	4.9	-	-	None	-	-
Hose Bib By Maintenance	SP	<2.5	-	-	None	-	-
Hose Bib By Boiler Room	SP	<2.5	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)



## Code Key

### Remediation Type Codes

FR	=	Fixture replacement
FRSLV	=	Replacement of fixture, supply lines, and valves
FRSLVPA	=	Replacement of fixture, supply lines, valves and plumbing assessment
SIGN	=	Warning sign posting
CAP	=	Remove fixture or cap line

### Room ID Codes

CC	=	Custodian Closet
MPR	=	Multi Purpose Room
Café	=	Cafeteria
Sci	=	Science Lab
PE	=	Physical Ed
BR	=	Bathroom
LR	=	Locker Room
RM	=	Room

### Fixture Type Codes

WF	=	Water Fountain
SK	=	Sink
SS	=	Slop Sink
SP	=	Spigot
PF	=	Pot Filler
HB	=	Hose Bib
IM	=	Ice Machine
WC	=	Water Cooler
SH	=	Shower

### Result Code

ND	=	Not Detected
<	=	Less Than
-	=	No Testing Required
#	=	When seen in the Post Remediation Test Results: after numerous failing tests, the Hashtag is used to show a passing result

